

DPW WORK REPORT

January 2021

- **Loss of signal issues with ice and possibly radios kept us in over the weekend. We had Roe Communications come in to check the signal strength of the radios. In 2015 we had them install new antennas and wire but the other electronics were installed by Windemuller electric but I don't remember the year. A bad lightning arrestor was keeping the radio from transmitting it full signal strength.**
- **The salt truck started showing warning lights last week. We took it to American Truck on M60 and they ordered a new cooling sensor for it. American Truck installed the sensor and also noticed a cracked belt and replaced that too.**
- **Christmas lights were taken down. We will need to order more replacement bulbs this summer.**
- **Belly blade on 05 dump truck seized up. A hinge on the right side froze up. We were able to order a redesigned replacement that helps keep water and salt out. We had to cut the old one off. Now working fine.**
- **Some snow plowing but nothing major so far.**
- **Meter reading done and all reports submitted to the State.**